




## BUILDING SAFETY CERTIFICATE

The building of Jeevan Jyoti School, Dhussara, Tehsil Amb District Una (HP) inspected by the undersigned officer along with concerned Junior Engineer (Chururu section) on dated 12-10-2021. It has been observed that no earthquake resistant provisions had been adopted in the building and no approved structural drawing from the competent authority produced at the time of inspection. Moreover no assistance was taken from Public work department for construction of building. Hence the structural safety of this building cannot be assured specially from earthquake resistance point of view. This department will not be held responsible for any type of loss of life and property etc. if this structure fails under any circumstances; however as per report of visual inspection of this building, it has been found safe at present only for a period Oct-2021 to Oct-2026 i.e. five years. *as per guide lines issued by the Spl. Secy (Pro) to the Govt of HP notification No PRW (B) E(3) 95/2019 dated 18/11/2019*

  
Junior Engineer  
Chururu Section

  
Assistant Engineer,  
B&R HPPWD Sub-division,  
Jole

  
Executive Engineer  
Bharwain Division  
HPPWD, Bharwain